
REMOVE SLATE @ LOW END OF VALLEY.
REMOVE DAMAGED PORTION OF COPPER

VALLEY FLASHING. (2.3)



TYPICAL DETAIL @ CHEEK WALL

SCALE: 1 1/2"= 1'-0"


ASK12

NOTE: ROOF SLATES TO BE SALVAGED & REINSTALLED WHERE POSSIBLE

MASTER LIST OF ALL DEMOLITION & CONSTRUCTION NOTES USED

NOTE: THE FIRST DIGIT IN HEXAGON INDICATES CSI DIVISION RESPONSIBLE FOR PROVIDING & INSTALLING WORK ITEM INDICATED. THE SECOND DIGIT DEFINES THE WORK TO BE PERFORMED

- 2.2 REMOVE & DISPOSE OF ITEMS INDICATED.
- $\langle 2.3 \rangle$ REMOVE & SALVAGE ITEM INDICATED FOR REUSE.
- (6.1) PROVIDE & INSTALL NEW ITEMS INDICATED.
- $\langle 7.1 \rangle$ PROVIDE & INSTALL NEW ITEMS INDICATED.
- $\langle 7.2 \rangle$ REINSTALL SALVAGED ITEMS INDICATED.



ROOF KEY PLAN

SCALE: 1/16" = 1'-0"


PHOTO #2

NOT TO SCALE

INSPECT SHEATHING & REPLACE W/ SOUTHERN (6.1)
YELLOW PINE PLANKS TO MEET & MATCH EXIST. AS REQUIRED. PROVIDE & INSTALL NEW SELF-ADHERING ICE & $\sqrt{7.1}$ WATER SHIELD, FELT, COPPER FLASHING TO MATCH EXIST., & REINSTALL SLATE SHINGLES (7.2) REMOVE SLATE @ THIS DORMER CHEEK WALL & 1 COURSE (MIN.) OF SLATE @ ADJACENT MAIN ROOF. REMOVE COPPER STEP FLASHING. 2.3 INSPECT SHEATHING & REPLACE W/ SOUTHERN (6.1) YELLOW PINE PLANKS TO MEET & MATCH EXIST. AS REQUIRED. PROVIDE & INSTALL NEW SELF-ADHERING ICE & WATER SHIELD, FELT, COPPER FLASHING TO MATCH(7.1)EXIST., & REINSTALL SLATE SHINGLES @ THIS 7.2

DORMER CHEEK WALL & ADJACENT MAIN ROOF

NOT TO SCALE



(6.1) PROVIDE & INSTALL NEW ITEMS INDICATED

(7.1) PROVIDE & INSTALL NEW ITEMS INDICATED

 $\langle 7.2 \rangle$ REINSTALL SALVAGED ITEMS INDICATED.

CENTER ROW APPROXIMATELY @ (7.1)—

ENLARGED ROOF PLAN @ NORTHWEST VALLEY & PHOTO KEY

SCALE: 1/2" = 1'-0"

RESTORATION OF EAVE CONDITION ABOVE 2ND FLOOR WINDOW

ASK13

ROOF KEY PLAN
SCALE: 1/16" = 1'-0"